STEERER ASSEMBLY

- Disassemble FLANGE from MOTOR
- Insert V-SEAL & FLANGE into SHAFT
- Insert SHAFT into CONNECTOR and fix by screw
- Fix FLANGE onto MOTOR by screw
- Insert V-SEAL onto FLANGE until V-SEAL & FLANGE keep same surface
- Assemble GASKET & PROPELLER onto SHAFT